




Zero automatically and select inches or mm. You can also zero on an OK sample to measure differences directly, eliminating mental arithmetic errors.



Press the operating lever to retract the barrel against the spring pressure. The gentle force will not crush soft materials or damage delicate samples.



Release the lever to close the barrel on the sample with constant spring pressure, eliminating errors due to operator technique. Read the large display to 0.0005 inches or 0.01 millimeters. Measure plates, blankets, packing, and substrates with ease and accuracy.

QUICK Mini Digital Micrometer

 **BETA INDUSTRIES**
The Quality Control Company

707 Commercial Ave.
Carlstadt, NJ 07072

Tel. 201-939-2400
www.betascreen.com